Work Orde May 7, 2010 10.	er ID 58469 :23:09 AM									Page
Item ID: Revision ID:	D4039-043		Accept					Setup Sta		
	Aft Bracket Assembly 07/05/2010			Cust Item I Customer:	D:			Sto	p	
Approvals:	Process Plan:	Date://5-0	7 Tooling:	D:	ate:	_	R	Run Sta	rt	
	QC:	Date:	SPC (Y/N):	Da	ate:			Sto	Р	
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr									
D4039	A									
			0.00				Ž.	n 65	/27	(4
Small Fab Small Fab	Memo 1- Assemble	lanyard to bracket as per d	0.00 lwg						/=-/	
110	OC5- Inspect part comple	eteness to sten on W/O	0.00							

QC

Quality Control

0.00

Identify as per dwg & Stock Location: 57172 0.00

Packaging

Memo

Memo

0.00

Packaging

120

Work Order ID 58469

May 7, 2010 10:23:09 AM



Page 2

Item ID:

D4039-043

Accept

Setup Start

Revision ID:

Item Name:

Aft Bracket Assembly

Start Date:

07/05/2010

Start Qty: 4.00

Required Date: 14/05/2010 Req'd Qty: 4.00



Date:

Cust Item ID:

Customer:

Reference:

Approvals:

QC:

Process Plan:

Operation

Description

Date:

Tooling: SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Start

Stop

Stop

Sequence ID/

Work Center ID

130

QC

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

Draw Number Draw Rev.

Plan Code

Reject Accept Qty Qty

Run

Reject Number

Insp. Stamp

CZ1015123

Quality Control

Picklist Print

May 7, 2010 10:23:14 AM

Work Order ID: 58469

D4039-043

Parent Item Name:

Aft Bracket Assembly

Comments:

Parent Item:

IPP RevA: new issue DD 09.12.15 verified by:EC



Start Date: 07/05/2010

Required Date: 14/05/2010

Page 1

Start Oty: 4.00

Paguired Oty 4 00

Comments: 1	IPP RevA: new issue DD 09.12.15 verified by:EC								Start Qty: 4.00	Required Qty: 4.00		
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Qty Issued	Date Issued	Status
04039-3 		Manufactured	No		B5847	0 4	Each	0.0000	1	£ 510	los p7	
D2690-6 		Manufactured	No			100 B58	Each 375	0.0000		500	5/27	
BLRS-010 		Purchased	No			100	Each	37.0000		80/	65 /27	
				Location		Loc Q		Loc Code		•		
					112689 113779		37 17 20			4		
MS27039-1-11 		Purchased	No			100	Each	81.0000		ZS10	105/27	
				Location		Loc Q		Loc Code			·	
				ST291	9662		81 81			<u>u</u>		
MS21042L3 		Purchased	No			100	Each	1,673.000		1510	105 p.z	***************************************
				Location ST300		<u>Loc Q</u> 16	<u>ty</u> 573	Loc Code			,	
				1	113537 113644 114523	ϵ	20 553 000		_	4		

Picklist Print

May 7, 2010 10:23:14 AM

Page 2

Work Order ID: 58469

Parent Item:

D4039-043

Parent Item Name:

Aft Bracket Assembly

Comments:

IPP RevA: new issue DD 09.12.15 verified by:EC

Start Date: 07/05/2010

Required Date: 14/05/2010

Start Qty: 4.00

Required Qty: 4.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch		rimary ocation	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Qty Issued	 Date Issued	Status
NAS1149D0363J		Purchased	No			100	Each	1,088.000	3	01	 /	

Washer

Location Loc Oty Loc Code ST298 1088 113288 2 114292 1086





